ISO Rules Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



Applicability

- 1 Section 304.8 applies to:
 - (a) the **operator** of a **transmission facility**;
 - (b) the operator of an electric distribution system;
 - (c) the operator of a facility that provides ancillary services;
 - (d) the operator of a generating unit that:
 - is not part of an aggregated generating facility;
 - (ii) has a **maximum authorized real power** rating greater than 4.5 MW; and
 - (iii) is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat, including a **generating unit** situated within an industrial complex that is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat;
 - (e) the operator of an aggregated generating facility that:
 - (i) has a **maximum authorized real power** rating greater than 4.5 MW; and
 - (ii) is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat, including an **aggregated generating facility** situated within an industrial complex that is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat;
 - (f) the **legal owner** of a **transmission facility**;
 - (g) the legal owner of an electric distribution system;
 - (h) the **legal owner** of a facility that provides **ancillary services**;
 - (i) the **legal owner** of a **generating unit** that:
 - (i) is not part of an aggregated generating facility;
 - (ii) has a maximum authorized real power rating greater than 4.5 MW; and
 - (iii) is directly connected to the transmission system or to transmission facilities within the City of Medicine Hat, including a generating unit situated within an industrial complex that is directly connected to the transmission system or to transmission facilities within the City of Medicine Hat;
 - (j) the legal owner of an aggregated generating facility that:
 - (i) has a **maximum authorized real power** rating greater than 4.5 MW
 - (ii) is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat, including an **aggregated generating facility** situated within an industrial complex that is directly connected to the **transmission system** or to **transmission facilities** within the City of Medicine Hat;

(collectively referred to as the "Responsible Entities")

and

(k) the **ISO**.

ISO Rules

Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



Requirements

Requirements to Perform Event Analysis

- 2(1) The ISO may conduct an event analysis of an event listed in Appendix 1.
- (2) The ISO may conduct an event analysis for an event that is not listed in Appendix 1 where:
 - (a) the **ISO** determines that an analysis is necessary to evaluate the impact of an event on the reliable operation of the **interconnected electric system**; or
 - (b) an event analysis report is requested by the **NERC** or the **WECC**.
- (3) The **ISO** may categorize the event using the highest applicable category in Appendix 1 where Category 1 is the lowest and Category 5 is the highest.

Event Analysis Requests

3 The **ISO** may request a brief report or an event analysis report or both from a Responsible Entity while conducting an event analysis.

Responsible Entity Reporting

- **4(1)** A Responsible Entity must provide the **ISO** with a report requested in accordance with subsection 3:
 - (a) in a manner specified by the ISO;
 - (b) within 10 **business days** if the **ISO** requests a brief report; and
 - (c) within 30 **business days** if the **ISO** requests an event analysis report.
- (2) Notwithstanding subsection 4(1), a Responsible Entity may request, in writing, including all relevant supporting documentation, that the **ISO** provide an extension to the time frames indicated in subsections 4(1)(b) and 4(1)(c):
 - (a) to allow for system restoration; or
 - (b) to allow the Responsible Entity to obtain accurate and complete information regarding the event.
- (3) The ISO must respond, in writing, to an extension request made in accordance with subsection 4(2) within 3 business days of receiving the request.

Review

- **5(1)** Upon reviewing a brief report or event analysis report provided in accordance with subsection 4, the **ISO** may request that the Responsible Entity provide additional information as required to complete the event analysis within a specified time frame.
- (2) A Responsible Entity must, upon receiving a request from the **ISO** under subsection 5(1) and within the time frame specified in the request:
 - (a) provide the **ISO** with the requested information; or
 - (b) notify the ISO, in writing, of the reasons for which the requested information is not available or the specified time frame cannot be met.

ISO Rules

Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



ISO Reporting

6(1) The **ISO** may, after reviewing the reports provided in accordance with subsection 4 and subsection 5, decide to author additional reports.

Event Analysis Recommendations

- 7(1) The ISO may, after completing a report under subsection 6, identify:
 - (a) the Responsible Entity required to implement each recommendation in the report; and
 - (b) an implementation date for each recommendation in the report.
- (2) The ISO may:
 - (a) provide a copy of a report issued under subsection 6 to each Responsible Entity identified under subsection 7(1); and
 - (b) advise each Responsible Entity identified under subsection 7(1), in writing, of the implementation date for each recommendation applicable to that Responsible Entity.
- (3) Subject to subsection 7(2), the **ISO** and each Responsible Entity identified under subsection 7(1) must treat a report provided under subsection 7(2)(a) as confidential.
- (4) Each Responsible Entity identified under subsection 7(1) must implement each applicable recommendation by resolving the outstanding issues associated with each recommendation on or before the implementation date.
- (5) Each Responsible Entity identified in subsection 7(1) must provide the ISO with:
 - (a) notification that the recommendation has been implemented in accordance with subsection 7(4) within 5 **business days** following such implementation, or
 - (b) a revised implementation date at least 5 **business days** before the implementation date identified by the **ISO** in subsection 7(2)(b), if the recommendation cannot be implemented in accordance with subsection 7(4).

Lessons Learned

- **8(1)** The **ISO** may complete a *Lessons Learned* document which includes the following information:
 - (a) high level details of the event;
 - (b) corrective actions for possible future events; and
 - (c) a list of lessons learned from the event.
- (2) A Lessons Learned document must not contain any of the following information:
 - (a) names of market participants;
 - (b) names of facilities;
 - (c) the date on which the event occurred; and
 - (d) to the extent practicable, any other information that would otherwise permit the identification of a **market participant** or facilities.
- (3) The ISO may publish the Lessons Learned document on the AESO website.

ISO Rules

Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



Requirement to Report to the NERC and the WECC

 ${f 9}$ The ISO may forward the reports and documents described in this section 304.8 to the **NERC** and the **WECC**.

Appendices

Appendix 1 – Event Categories

Revision History

Date	Description
2020-09-16	Revised to add subsections 1(i)(ii) and 1(j)(i).
	Administrative amendments.
2018-04-30	Initial release

ISO Rules Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



Appendix 1

Event Categories

Category 1: An event that results in one or more of the following:

- (a) An unexpected sustained outage caused by a common disturbance and contrary to design of any combination of three or more transmission facilities, aggregated generating facilities or generating units with an aggregate generation of 500 MW to 1,999 MW at the time of the outage.
- (b) Failure or misoperation of a **remedial action scheme**.
- (c) A system wide voltage reduction of 3% or more that lasts more than 15 continuous minutes due to an emergency on the **interconnected electric system**.
- (d) Unintended separation within the interconnected electric system that results in an island of 100 MW to 999 MW. Excludes transmission system radial connections, and electric distribution system level islanding.
- (e) The loss of monitoring or control that significantly affects a Responsible Entity's ability to make operating decisions for 30 continuous minutes or more, including:
 - loss of operator ability to remotely monitor or control elements of the bulk electric system, aggregated generating facilities or generating units connected to the bulk electric system;
 - loss of communications from supervisory and data acquisition remote terminal units for a substation rated 69 kV and above;
 - (iii) unavailability of inter **control centre** protocol links reducing **bulk electric system** visibility
 - (iv) loss of the ability to remotely monitor and control generating units providing regulating reserves; or
 - (v) state estimator or contingency analysis failing to solve at a control centre for:
 - (A) the ISO; or
 - (B) the operator of a transmission facility.

Category 2: An event that results in one or more of the following:

- (a) Complete loss, for 30 minutes or more, of all voice communication systems for a **control centre** including a **control centre** for:
 - (i) the ISO;
 - (ii) the **operator** of a **transmission facility** (that controls **transmission facilities** at 2or more locations); or
 - (iii) the **operator** of a **generating unit** (that controls **generating units** at 2 or more locations).
- (b) Operating voltage excursions at the **point of connection** equal to or greater than 10% lasting more than 15 continuous minutes.
- (c) Unintended separation within the **interconnected electric system** that results in an island of 1,000 MW to 4,999 MW.

ISO Rules Part 300 System Reliability and Operations Division 304 Routine Operations Section 304.8 Event Analysis



- (d) Unintended loss of 300 MW or more of firm load for more than 15 minutes.
- (e) Interconnection reliability operating limit Tv violation.

Category 3: An event that results in one or more of the following:

- (a) Unintended loss of load or generation within the interconnected electric system of 2,000 MW to 5,000 MW.
- (b) Unintended separation within the **interconnected electric system** that results in an island of 5,000 to 10,000 MW. Excludes the loss of **interconnections**.

Category 4: An event that results in one or more of the following:

- (a) Unintended loss of load or generation within the interconnected electric system of 5,001 MW to 9,999 MW.
- (b) Unintended separation within the **interconnected electric system** that results in an island of more than 10,000 MW. Excludes the loss of **interconnections**.

Category 5: An event that results in one or more of the following:

- (a) Unintended loss of load within the interconnected electric system of 10,000 MW or more.
- (b) Unintended loss of generation within the **interconnected electric system** of 10,000 MW or more.